

CBLOOM/RV50
RAVEN 5000 CONTROL
ADAPTOR LOOM

NOTES:

1. SERVO VALVE WIRES MAY NEED TO BE REVERSED AT PINS 1 & 3 IN 24 PIN CONNECTOR ON CBLOOM/RV50 TO CONFIRM CORRECT SERVO VALVE OPERATION

14th FEBRUARY 2011

CROPLANDS